

# Known Issues

This article summarizes known issues and workarounds for reported issues in Raynet One UEM 3.2.

- 1 [Products tab in security assessment devices has bad vulnerability count](#)
- 2 [UEM device security summary report - Drilldown not working](#)
- 3 [RayVentory Server integration blocks complete UEM until timeout](#)
- 4 [Automatic generation of folder structure ignores creation constraints](#)
- 5 [The 'Save changes' button is not active when deleting an item in 'Custom properties' settings](#)
- 6 [Search function and filter not working in IT visibility report](#)
- 7 [Third-party patching does not delete folder structure](#)
- 8 [Azure scheduled task execution does not contain imported and updated users](#)
- 9 [Delay on 'Edit dependency' dialog of managed package](#)

---

## Products tab in security assessment devices has bad vulnerability count [🔗](#)

### Applies to:

Raynet One UEM 3.2 with catalog integration enabled

### Description:

When catalog integration is enabled and inventories got enriched, then the vulnerability count of a product by device is incorrect. Instead, the total vulnerability count is displayed.

### Workaround:

Alternatively, the vulnerability count of a product on a device can be viewed through device details on endpoints, in the software tab.

### Reference:

RDEP-304

---

## UEM device security summary report - Drilldown not working [🔗](#)

### Applies to:

Raynet One UEM 3.2

### Description:

The shared report "UEM device security summary" does support drill down, instead the report component becomes unresponsive.

### Workaround:

Currently none.

### Reference:

RDEP-360

---

## RayVentory Server integration blocks complete UEM until timeout [🔗](#)

### Applies to:

Raynet One UEM 3.2

### Description:

When integration cannot be established due to wrong/outdated credentials until timeout happens UEM is unresponsive.

**Workaround:**

Currently none.

**Reference:**

RDEP-340

---

## Automatic generation of folder structure ignores creation constraints [↗](#)

**Applies to:**

Raynet One UEM 3.2

**Description:**

Currently UEM does not allow creating the same folder name on the same level. However, one can override this by using the automatic generation of folders in exe packages.

**Workaround:**

Currently none.

**Reference:**

RDEP-282

---

## The 'Save changes' button is not active when deleting an item in 'Custom properties' settings [↗](#)

**Applies to:**

Raynet One UEM 3.2

**Description:**

On package edit dialog, when a custom property is deleted the 'Save changes' button is not activated.

**Workaround:**

Increasing the package version activates the 'Save changes' button.

**Reference:**

RDEP-358

---

## Search function and filter not working in IT visibility report [↗](#)

**Applies to:**

Raynet One UEM 3.2

**Description:**

Free text filtering is not available in hardware overview of IT Visibility report. Further, search functionality is not working on operating system column.

**Workaround:**

Currently none.

**Reference:**

RDEP-357

---

## Third-party patching does not delete folder structure [🔗](#)

### Applies to:

Raynet One UEM 3.2

### Description:

In third-party patching, when configured to delete the previous package, the parent folder is not removed and remains empty.

### Workaround:

Manual removal of the previous folder structure.

### Reference:

RDEP-332

---

## Azure scheduled task execution does not contain imported and updated users [🔗](#)

### Applies to:

Raynet One UEM 3.2

### Description:

Azure scheduled task execution summary miss information on imported and updated users.

### Workaround:

Currently none.

### Reference:

RDEP-303

---

## Delay on 'Edit dependency' dialog of managed package [🔗](#)

### Applies to:

Raynet One UEM 3.2

### Description:

When 'Edit dependency' dialog is opened and dependency field is empty and it is populated in the background. The user can misinterpret as this field to be empty.

### Workaround:

Depending on the data, the field get populated at max. 30 seconds.

### Reference:

RDEP-343